



Gutter 1




Block A

PJM Roofer



Gutter 2




Block B

PJM Roofer




Gutter 3




Block C


PJM Roofer



Gutter 4




Block D



Gutter 5


PJM Roofer

Block E




Gutter 6

Block F




Gutter 7

Block G



Gutter 8


PJM Roofer



PJM Roofing


PJM Roofer

Office



PJM Roofer

PJM Roofer



PJM Roofer

1)  - **Fibreglass translucent sheet - good condition**

2)  - **Fibreglass translucent sheet - moderate condition**

3)  - **Fibreglass translucent sheet - bad condition**

4)  - **Replace old gutter**

5)  - **Capping along gutter**

6)  - **Capping along chimney**

7)  - **Replace old 14" turbine ventilator**

8)  - **Replace old 18" turbine ventilator**

PJM Roofer